

# New York State Department of Transportation

## PIA Safety Flag NB23CTW008

By: Rehan Afridi

Flag Date: June 14, 2023

Superseding Information:

No Flags Superseded

### Structure Information

**BIN: 1065318**

**Feature Carried: 278I278IX2M23027**

**Feature Crossed: 6TH AVENUE**

**Orientation: 8 - NORTHWEST**

**Region: 11 - NEW YORK CITY**

**County: KINGS**

**Political Unit: City of NEW YORK**

**Approximate Year Built: 1962**

**Posted Load Matches Inventory : Yes**

**Bridge Load Posting (Tons) : Not Posted for Load**

**Primary Owner: New York State Department of Transportation**

**Primary Maintenance Responsibility: 12 - State - Subcontracted to another Party**

**Typical or Main Span Type: 3 - Steel, 02 - Stringer/Multi-Beam or Girder**

**This Bridge is not a Ramp**

**Number of Spans: 322**

### Verbal Notification Information

**Person Notified: Muhammad Mubeen**

**Date: June 14, 2023 1:45:00 PM**

**Of: NYSDOT Region 11**

### Signature Information

**Signature: Rehan Afridi, P.E. 075185**

**Date: June 16, 2023**

**Reviewed By: Robert Kemp**

**Date: June 16, 2023**

**Attachments: 5**

***Flagged Elements*****No Flagged Elements*****Flagged Condition Description***

This PIA Safety Flag No. NB23CTW008 is a New Flag.  
Location: Span 158, Pier 157, Column C1 at the base.

At Span 158, Pier 157 Column C1, End face, there is a corroded and broken electrical junction box which exhibits exposed live wires. The condition is at the base of the column, and is accessible by the public.

The subject location is at 40th Street and 3rd Avenue westbound.

**Flag Photographs**

Photo Number: 1


Photo Filename: **Flag Location - Span 158 RA.jpg****Attachment Description: Flag Location Plan.**

Photo Number: 2

Photo Filename: IMG\_2716.JPG



**Attachment Description: General view of Flagged location. Looking Begin.**



Photo Number: 3

Photo Filename: IMG\_2717.JPG




**Attachment Description:** Location of Flagged condition at Pier 157, Column C1. Looking Begin.



Photo Number: 4

Photo Filename: IMG\_2718.JPG




**Attachment Description:** Close-up view of the broken junction box at Column C1. Looking Begin.



Photo Number: 5

Photo Filename: IMG\_2719.JPG



**Attachment Description:** Non-contact voltage detector indicates live wires at the junction box. Looking Begin.